Com 2 of 7

21 August 1961

TENORANDEM FOR: Chief, Development Branch, DPD-DD/P : Insulation and Ventilation of Hangars 4,5 and 6 25X1A SHEJECT 2095 (IN 14724) REFERENCE 25X1A 1. A review of section estimate for installing insulation in hangers and painting roofs of hangers has been completed. The costs submitted by the in reference are as follows: 25X1A 25X1A 2. We recommend the following be accomplished in lieu of to insulate and paint the reefs of the three 25X1A spending hanwers: e. Install ridge ventilators in each hanger. Install side ventilators with manually operated lowers out inside of hangers above the roof of the lean-to and shop. These to be of sufficient size to equal the discharge of the ridge ventilators. The roof ventilator will expel the trapped hot air in the roof of the building and cause circulation of air from the fleor to the roof. b. Place pedestal type fans in the hangers for greater circulation. 3. We believe that the ventilators and pedestal type fans will provide sufficient cooling for hangers. However, if necessary during the extreme het weather, inexpensive sprinklers can be added

to the roof to aid in ecoling.

25X1A

25X1A

4. The estimate for the installation of ventilators is approximately per hangar. Flans and a firm cost estimate to this office. It is recommended that will be substitted by be included in your activity Progrem. funds in the secent of

25X1A

25X1A

25X1A

Deputy for Special Projects Materiel Staff, DFD-DD/F

MAKATO

0XC-2141

SUBJECT: Insulation and Ventiletten of Hangara 4,5 and 6

CONCURRENCE:

the second

25X1A

25 AUG 1

STANLEY W. BEEFLI

Colonel USAF Acting Chief, DPD-DD/P

2'U AUG 1904

JAMES A. CURNINGRAM, JR. Assistant Chief DPD-DD/P

25X1A

Chief, Special Projects Branch
DPP-DD/P

25X1A

Installations Engineer Material Staff DPD-DD/P

25X1A

HS/DPD-DD/

Distribution

LOy 1 & 2 - Addresses

3 - &C/DPD

4 - AUST CHIDPD

5 - C/SPB/DPD

6 - C/MS/DMD

7 - KI/DPD